

Discontinuation for Specific Snap-in Capacitor Part Numbers 5-21

380LQ152M080H022

380LX822M035J032

381LQ151M450H042

381LR101M400H022

381LX101M450J022

381LX102M080J012

381LX103M035J052

381LX121M400J022

381LX122M100H032

381LX182M080H032

381LX182M080H042

381LX182M080J032

381LX272M050J012

381LX820M400H012

SLP101M450A5P3

SLP101M450C3P3

SLP103M063H4P3

SLP122M200H5P3

SLP181M250C1P3

SLP182M200H4P3

SLP331M200C3P3

SLP331M450H7P3

SLP332M080C4P3

SLP471M450H9P3

SLP472M063H3P3

SLP681M200C7P3

SLPX101M385A3P3

SLPX102M250E9P3

SLPX102M250H5P3

SLPX123M050H7P3

SLPX152M200H4P3

SLPX331M200A3P3

SLPX471M200C3P3

SLPX471M450H9P3